

UNITED STATES PATENT AND TRADEMARK OFFICE

UNITED STATES DEPARTMENT OF COMMERCE United States Patent and Trademark Office Address: COMMISSIONER FOR PATENTS P.O. Box 1450 Alexandria, Virginia 22313-1450 www.uspto.gov

BIBDATASHEET

Bib Data Sheet

CONFIRMATION NO. 4506

Bib Data Sneet									
SERIAL NUMB 10/669,754	i i		(CLASS 123	GROUP ART UNIT 3747		ATTORNEY DOCKET NO. 11610-55-DIV2		
APPLICANTS							,		
Gary E. Mo	orrisse	ette, Orlando, FL;			Q.	\$C>			
APPLICANTS Gary E. Morrissette, Orlando, FL; Reginald L. Browning, Orlando, FL; ** CONTINUING DATA *********************** This application is a DIV of 10/283,015 10/29/2002 PAT 6,651,637 ** FOREIGN APPLICATIONS ************************************									
** FOREIGN APF	cation PLICA	\	***		,637			BLE	COPY
Foreign Priority claimed 35 USC 119 (a-d) conditions			STATE OR COUNTRY FL			TOTA CLAIN 33	ИS	: INDEPENDENT CLAIMS 3	
ADDRESS RICHARD K. WA Allen, Dyer, Dopp P.O. Box 3791 Orlando , FL 32802-3791		ER illbrath & Gilchrist, P.A							
TITLE Vehicle ignition s	ystem	using ignition module	with red	uced heat gene	eration				
	FEES: Authority has been given in Paper No. to charge/credit DEPOSIT ACCOUNT						6 Fees () essing Ext. of

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.